



# It was sabotage! Russia finds International Space Station hole was made **DELIBERATELY**, possibly by agent of Elon Musk says agency chief

- The ISS experienced a drop in pressure due to an air leak overnight to August 30
- Various theories were floated, including damage caused by a micrometeorite
- However, an initial investigation has ruled-out accidental damage as an option
- A second probe aims to reveal further details, including persons responsible

By [HARRY PETTIT FOR MAILONLINE](#)



6

share  
s

21

View commen  
ts

Russian investigators looking into the origin of a hole that caused an oxygen leak on the International Space Station say it was caused deliberately.

Speaking on Monday, Dmitry Rogozin, the head of Russian space agency Roscosmos, said that an official investigative report had confirmed their theory.

'It concluded that a manufacturing defect had been ruled out which is important to establish the truth,' he said.

 Sabotage: Russian astronaut Sergei Prokopyev showed the original 'drilled hole' during a video released by the space agency Roscosmos

Sabotage: Russian astronaut Sergei Prokopyev showed the original 'drilled hole' during a video released by the space agency Roscosmos

---

Rogozin said the commission's main line of inquiry was that the hole had been drilled deliberately, a position that has been voiced in the past.


'Where it was made will be established by a second commission, which is at work now,' he said.

Officials are hoping that secondary investigation will identify the people or persons responsible.


---

## SHARE THIS ARTICLE


## RELATED ARTICLES




The motorcycle that drives ITSELF: BMW unveils a video of



Lost narwhal that strayed too far from the Arctic adopted



iPhone owners who want to use regular headphones will



YouTube Kids gives parents greater control over what




---

The small hole in the wall of a Russian-made Soyuz capsule docked onto the ISS was located in August and quickly sealed up.

Officials suggested a number of possible reasons for the appearance of the hole.

Initially, it was thought the damage could have been caused by a micrometeorite piercing the spacecraft.

Another anonymous source said the whole was drilled by a worker who hid their mistake with a seal instead of reporting it.

 Sergei Prokopyev (pictured) explained on a video released by Roscosmos located and sealed the tiny hole that created a slight loss of pressure  

**Sergei Prokopyev (pictured) explained on a video released by Roscosmos located and sealed the tiny hole that created a slight loss of pressure** 

 The Soyuz MS-08 (pictured) left Earth on March 21 to transport three members of the Expedition 55 crew to the International Space Station 

**The Soyuz MS-08 (pictured) left Earth on March 21 to transport three members of the Expedition 55 crew to the International Space Station**


The Russian media even speculated that a US astronaut might have sabotaged the spacecraft to delay a possible early return to earth due to alleged sickness of one member of the ISS crew.

Rogozin even held phone talks with NASA Administrator Jim Bridenstine.

They men later released a joint statement which said: 'The Administrator and the General Director noted speculations circulating in the media

regarding the possible cause of the incident and agreed on deferring any preliminary conclusions and providing any explanations until the final investigation has been completed.

'They affirmed the necessity of further close interaction between NASA and Roscosmos technical teams in identifying and eliminating the cause of the leak, as well as continuation of normal ISS operations and NASA's ongoing support of the Roscosmos-led Soyuz investigation. They acknowledged the entire crew is dedicated to the safe operation of the station and all docked spacecraft to ensure mission success.

A screenshot of a social media post. The text reads: "Roscosmos director Dmitry Rogozin said that the hole could have been drilled during manufacturing or while in orbit". To the right of the text is a share icon and a grey button with "+5".

**Roscosmos director Dmitry Rogozin said that the hole could have been drilled during manufacturing or while in orbit**

---

'The Administrator and the Roscosmos General Director agreed to conduct their first face-to-face meeting at the Baikonur Cosmodrome on or about Oct. 10 when the NASA Administrator will visit Russia and Kazakhstan in conjunction with the upcoming Soyuz crew spacecraft launch of American astronaut Nick Hague and Russian cosmonaut Alexy Ovchinin.'

Previously, Rogozin - who once oversaw the space industry as deputy prime minister - admitted it had become difficult to work with NASA.

'Problems with NASA have certainly appeared but not through the fault of NASA,' he said, blaming unnamed American officials for telling the US space agency what to do.

He also claimed that SpaceX founder Elon Musk sought to squeeze Russia out of the space launch services market and complained about the US military drone X-37.

'Americans have this thing, the X-37,' Rogozin said. 'We don't understand its purposes. Rather, we do understand, but we have not received an official explanation.

'Essentially, this thing can be used as a weapons carrier.'